

Versión 1.0

- Primera versión.

Versión 1.1

- Control avanzado de clima.
- Objeto de estado de temperatura medida por la máquina.
- Código de LEDs para indicar errores.
- Contador de horas de funcionamiento.
- Ordenación de objetos de forma más lógica.

Versión 1.2

- Nueva funcionalidad: se añade el modo silencio, consistente en una velocidad inferior a la mínima*
- Corrección de una incidencia: algunas máquinas en lugar de enviar la temperatura ambiente correcta, envían 0 °C por lo que el algoritmo de gestión avanzada del clima no funciona. Se implementa un algoritmo que impide utilizar el control avanzado de temperatura si la temperatura recibida es de 0 °C.

*Compatible sólo con las máquinas que dispongan de dicha funcionalidad, consultar el manual para más información.

Versión 1.3

- Se soluciona un problema de compatibilidad con las unidades FTXJ-A en las que el KLIC reporta error de comunicación

Versión 1.4

- Corrección de una incidencia: no se guarda la consigna en el salvado de escenas
- Se añade un parámetro para seleccionar si las escenas guardadas se sobrescribirán o no en la siguiente descarga.

Versión 1.5

- Aumento de la compatibilidad con unidades interiores.
- Cambio del valor por defecto del parámetro "Escenas tras descarga".

Version 1.0

- Initial version.

Version 1.1

- New functionality added:
 - Advanced climate control.
 - Status object of the internal unit temperature.
 - Error notifications through LED code.
 - AC unit operation time counter.
 - Objects ordered in a logical way.

Version 1.2

- New functionality: silence mode is included, this is a fan speed lower than the minimum*.
- Bug fix: certain indoor units do not measure properly the ambient temperature, sending 0 °C instead of the real temperature and affecting directly the Advance Temperature Management when enable. To avoid this malfunctioning an algorithm which avoids the usage of the Advance Temperature Management mode when the temperature measured by the indoor unit is 0°C has been implemented.

*Check compatibility with Daikin unit, Not every indoor unit model has this functionality.

Version 1.3

- Bug fix: communication issue with units FTXJ-A, KLIC-DD reports communication error.

Version 1.4

- Bug fix: setpoint value was not stored when learning a scene.
- A new parameter has been added to select if the saved scenes are overwritten in the following download.

Version 1.5

- Increased compatibility with indoor units.
- Changed the default value of the "Scenes after download" parameter.