

Versión 1.0

- Primera versión.

Versión 1.1

- Corrección de una incidencia no relacionada con la funcionalidad detectada al certificar el producto

Versión 2.0

- Corrección de una incidencia: No es posible controlar algunas unidades MMD-AP0096BHP1-E. Error de comunicación.
- Cambio en el módulo de funciones lógicas: debido a temas de certificación, para cada dato de entrada que se defina hay que seleccionar el tipo de dato.

Versión 2.1

- Nueva versión para compatibilizar el programa de aplicación con un nuevo microcontrolador que se montará en este dispositivo debido a la escasez de componentes.
- Este micro se comienza a montar a partir del número de serie: **21AST0001** . La utilización de este programa de aplicación es obligatoria a partir de dicho número de serie.
- Corrección de incidencias menores

Version 1.0

- Initial version.

Version 1.1

- Bug fix detected in the certification process.not related with the functionality

Version 2.0

- Bug fix: Due to communication error, it is not possible to control some units MMD-AP0096BHP1-E.
- Logical function module change: due to KNX certification issue it is necessary to select each DPT for the data entries defined.

Version 2.1

- New application program version to have compatibility with the new microcontroller we are mounting on the devices from serial number **21AST0001**
- This application program is compatible with lower serial numbers, but from this serial number on only this application program can be used.
- Minor bug fix.