

Z41 COM FW

Versión 1.0.0

- Compatibilidad con aplicación 1.0.

Versión 1.0.1

- Corrección de una incidencia: un botón fantasma te lleva a una página en blanco.
- Corrección de una incidencia: la pantalla queda bloqueada si es pulsada en modo noche.

Versión 1.1.0

- Compatibilidad con aplicación 1.1.

Versión 1.1.1

- Corrección de una incidencia: no se escucha el audio de GetFace IP en Z41 COM.

Versión 1.2.4

- Compatibilidad con aplicación 1.2.

Versión 1.2.5

- Ajustes menores para cumplir con normativas.

Versión 1.3.0

- Compatibilidad con aplicación 1.3.

Versión 1.3.1

- Solución de una incidencia: las Z41 COM dejan de responder a la IP de voIP que se les ha asignado y por lo tanto reciben las llamadas del vídeo portero

Version 1.0.0

- Compatibility with application 1.0.

Version 1.0.1

- Bug fix: a ghost button takes the user to a blank screen.
- Bug fix: the device gets blocked when pressed in night mode.

Version 1.1.0

- Compatibility with application 1.1.

Version 1.1.1

- Bug fix: Intercom audio is muted on Z41 COM.

Version 1.2.4

- Compatibility with application 1.2.

Version 1.2.5

- Minor fixes as to meet regulations.

Version 1.3.0

- Compatibility with application 1.3.

Version 1.3.1

- Bug solving: Z41 COM does not reply to a ping request of the voip IP assigned, therefore, it does not receive calls from intercom.